



NOTICE TO CONTRACTORS



Date: January 20, 2011

Subject: Seawall Weep Holes

From today forward, all weep holes must be a minimum of 2" in diameter, per Ord. 10-02, and have filter fabric permanently mounted on the land side of each weep hole.

Please advise your engineers to show this information on the plan.

Thank you,

Robert Mahar
Building Official