



NOTICE TO CONTRACTORS



Date: 12/10/2007

Subject: Helical Tieback Systems for Seawall Maintenance

The specifications for DSMS Helical Tieback Systems do not allow for the system to be used to repair a failed seawall. In order to make sure the system is not proposed for use on a failed seawall the City will assess a fee of \$35.00 for a pre-inspection of the seawall.

The inspection will be performed as part of the review process. The \$35.00 pre-inspection fee will be charged at application submittal, as well as the standard plan review fee.

The permit will not be issued unless the seawall is approved for maintenance type repairs. If the seawall is determined to have failed, the contractor will be notified in writing that the permit cannot be issued and Code Compliance will be notified.

Thank you,

Robert Mahar
Building Official

